

---

## CooVox U50 V1.1.2 Changelog

### Read Before Upgrade:

- ♦ This patch is only intended for upgrading to CooVox-U50 V1.1.2. Please check details of this release and decide if it is necessary to upgrade your system.
- ♦ Firmware version should be V1.1.0 or higher. (P.S.: You can upgrade from V1.1.0 to V1.1.2 directly).
- ♦ A Configuration file is not included in the upgrade so you are not required to backup your configuration before upgrading. If a previous version of backup file is restored after upgrade, it will lead to abnormal GUI functionality. You should however create a new backup file once you have upgraded to V1.1.1.
- ♦ Clear your browser cache after upgrade to display the firmware version correctly.

### Background Fixed:

1. Fixed the bug which modifying or deleting SIP trunk can cause system exception
2. Changed path of the system logs
3. Fixed the bug which IVR cannot playback by extensions with SIP and IAX2 protocols enabled
4. Fixed PPTP and L2TP client disconnection problem
5. Fixed Tehran time zone bug

### GUI Fixed

6. Added Static Route for VLAN
7. Renewed Auto provision of Htek phones(Adjustment and new model support)
8. Optimized firewall functionalities
9. Adjusted Call Logs page for allowing filter with queue numbers and ring group numbers

### GUI Added

10. Added distinctive ringtone support for Port DID and Number DID
11. Added "Web Dial Auto-Answer" option for Web extension login GUI, to enable/disable auto answer of the extension number while dialing from Web GUI.